



# SpotMe® Quick Installation Guide

## Start Kit Port 1S (1 Sensor 1 Warning Unit)

- Open the box and check the contents
  - 1 Warning Unit
  - 1 IR Sensor
  - 2 User Manuals
- Power supply for the Warning Unit
  - 230/6V Converter + UK adaptor or
  - Battery Module
  - 1m Cable
  - Battery charger
- Install the Warning Unit
  - Place it on the wall in a visible position
  - Mount is high enough so trucks don't hit it
  - Screw the bracket to the wall
  - Connect the power supply, check flashing
- Install the sensor
  - Put sensor at recommended distance to the Port/Gate, see table.
  - Tape it to the wall at 1,5 m height
  - Arrow should point to the Port
  - The sensor makes now an auto calibration
  - After 2 minutes - Test the system!
- System test
  - Pass the sensor with a real object in normal speed.
  - The Warning Unit should flash for 5 seconds
  - Study the traffic during 20 minutes
  - If the sensor detects other traffic the sensor field can be shortened:
    - Place at 2,5 m height
    - Angle it down
  - Fix the sensor in final position with screws
- Finished



Port with 1 Sensor 1 Warning unit



Kit with Electric Converter  
Parts N° 7547939



Kit with Battery  
(for demo purpose)  
Parts N° 7547951

Object speed	Sensor distance
1 m/s (3,6 Km/h)	> 3 m
2 m/s (7,2 Km/h)	> 6 m
3 m/s (10,8 Km/h)	> 9 m
4 m/s (14,4 Km/h)	> 12 m

Distance between Sensor and Warning Unit



IR Sensor Indoor